

**Earth Solutions NW LLC**

15365 NE 90th Street, Suite 100
Redmond, WA 98052
Main (425) 449-4704 | Fax (425) 449-4711
www.esnw.com

DAILY FIELD REPORT

ESNW Rep. AJL	Project No. 2953.20	Page 1 of 1	Report No. 42v
Time On Site 10:00	Time Off Site 10:30	Date 2/8/21	Day of Week Monday
Travel Time 1 hr.		Weather 45°F, Cloudy	

Project Name Westridge SF North (Vertical)	Job Location NE Discover Dr. & 9 th Ave NE, Issaquah	Client/Owner Polygon – WLH, Inc	
Contractor #1	Contact	Field Supervisor LAC	Reviewed
Contractor #2	Contact	Project Manager SHA	Reviewed SHA

Are approved plans/permits on site?	Project No.	Permit No.
-------------------------------------	-------------	------------

Footing or Caisson Subgrade	Conditions Observed
Lot 60	Dense to very dense

As requested, ESNW rep was onsite to probe footing subgrade for lot 60. While on site, ESNW rep observed the following:

Lot 60 Subgrade

While onsite, ESNW rep observed that the contractor had brought lot 60 to footing grade. ESNW rep probed the excavated footing subgrade using a ½" diameter steel T-probe. ESNW rep observed dense to very dense soil conditions in the probed areas. These observed conditions are considered suitable for the support of the proposed SFR structure.

ESNW rep will return when requested.

Adrien Leland
ESNW Assistant Field Supervisor

NOTE: The ESNW rep. has observed only the footing and/or caisson excavations listed above. If any change in the subgrade conditions occur, we should be promptly notified.